



Supply Checklist

Items you will need before leaving with your first load

1. Parts Room (MO: Bay #47, PA: Bay #24, UT: Bay #7)

- Oil and Antifreeze
- Spare Fuses, Headlight Bulbs, and Glad Hand Seals
- Pair of Wiper Blades
- Extra key

2. Company Store

- Time In/Time Out Stamp
- Pulp Thermometer (Refrigerated Division Only)
- Abloy Locks: Large Lock, Small Lock
- Air Cuff Lock (Truck Anti-Theft Device)
- Atlas
- Jumper Cables
- Safety Vest
- Gloves (Optional)
- Small Set of Tools (Optional)
- Glad Hand Air Hose (Optional)

3. Drivers Lineup (MO: Plaza Building, PA: Plaza Office, UT: Shop)

FLATBED, INTERMODAL, HOPPER, REEFER (UT & PA), TANKER

- Comcheks
- Trip Sheets
- Permit Book (Permit Department)
- Paper Log Book (Logs Department)

REEFER (MO ONLY)

- Permit Book (Permit Department)

MO Orientation ONLY: Flatbed drivers need to apply for your TWIC Card prior to departing.

All other divisions, it is not required, but you can apply for a TWIC card at the MO Terminal TWIC office is located in the Permit Department in the Plaza. You will need two forms of identification to apply.

MO (Flatbed, Intermodal, Hopper, Tanker), PA and UT:

After completing #1-3 above and have been assigned your first load, pick up your trailer and complete #4 by pulling into an Outbound Bay.

4. Outbound Bay (PA: Bays #8,9; UT: Bays #1-8)

- Load Locks
- Tire Chains
 - Refrigerated and Tanker: 2 Super Single Chains, 1 Super Single Cable, 1 Dual Cable -
 - Flatbed: 2 Super Single Chains, 1 Dual Cable
- Door Seals
- Anti-Gel

MO - REEFER ONLY - BOBTAIL to Plaza Building Bay #14

(If no one is there, check upstairs in the flatbed equipment office.)

In this bay, the equipment that you will need has been organized for you. It will include: Comcheks, Trip Sheets, Paper Log Book, Load Locks, Tire Chains, Door Seals.