

Supply Checklist

Items you will need before leaving with your first load

1. Parts Room (MO: Bay #47, PA: Bay #24, UT: Bay #7)

- Oil and Antifreeze (also available in the Plaza)
- Spare Fuses, Headlight Bulbs, and Glad Hand Seals
- Pair of Wiper Blades
- Extra key

2. Company Store

- Time In/Time Out Stamp
- Pulp Thermometer (Refrigerated Division Only)
- Abloy Locks: Large Lock, Small Lock, and Air Cuff Lock
- Atlas
- Jumper Cables
- Safety Vest
- Gloves (Optional)
- Small Set of Tools (Optional)
- Glad Hand Air Hose (Optional)

3. Drivers Lineup (MO: Plaza Building, PA: Plaza Office, UT: Shop)

- Comchecks
- Trip Sheets
- Permit Book (Permit Department)
- Paper Log Book (Logs Department)

MO Orientation ONLY: Don't forget to sign up for your TWIC Card and Passport prior to departing.

After completing #1-3 above and have been assigned your first load, pick up your trailer and complete #4 by pulling into an Outbound Bay.

4. Outbound Bay (MO: Bays #6,7,8 ; PA: Bays #8,9; UT: Bays #1-8)

- Load Locks
- Tire Chains
 - Refrigerated and Tanker: 2 Super Single Chains, 1 Super Single Cable, 1 Dual Cable
 - Flatbed: 2 Super Single Chains, 1 Dual Cable
- Door Seals
- Anti-Gel

*Thank you for completing this checklist.
We wish you a safe and enjoyable first trip!*