
(800)321-4552 www.primeinc.com



Supply Checklist

Items you will need before leaving with your first load

1.Parts Room (MO: Bay #47, PA: Bay #24, UT: Bay #7) ☐ Oil and Antifreeze ☐ Spare Fuses, Headlight Bulbs, and Glad Hand Seals ☐ Pair of Wiper Blades ☐ Extra key	
2.Company Store	_
☐ Time In/Time Out Stamp ☐ Pulp Thermometer (Refrigerated Division Only) ☐ Abloy Locks: Large Lock, Small Lock ☐ Air Cuff Lock (Truck Anti-Theft Device) ☐ Atlas	 ☐ Jumper Cables ☐ Safety Vest ☐ Gloves (Optional) ☐ Small Set of Tools (Optional) ☐ Glad Hand Air Hose (Optional)
3. Drivers Lineup (MO: Plaza Building, PA: Plaza Office, UT: S	
FLATBED, INTERMODAL, HOPPER, REEFER (UT & PA), TA	ANKER
☐ Comcheks☐ Trip Sheets☐ Permit Book (Permit Department)☐ Paper Log Book (Logs Department)	
REEFER (MO ONLY)	
☐ Permit Book (Permit Department)	
MO Orientation ONLY: Don't forget to sign up for your TWIC Card prior to departing.	
MO (Flatbed, Intermodal, Hopper, Tanker), PA and UT: After completing #1-3 above and have been assigned your first load, pick up your trailer and complete #4 by pulling into an Outbound Bay.	
4.Outbound Bay (PA: Bays #8,9; UT: Bays #1-8) □ Load Locks □ Tire Chains -Refrigerated and Tanker: 2 Super Single Chains, 1 Super S Flatbed: 2 Super Single Chains, 1 Dual Cable □ Door Seals □ Anti-Gel	Single Cable, 1 Dual Cable -
MO - REEFER ONLY - BOBTAIL to Plaza Building Bay #14	
(If no one is there, check upstairs in the flatbed equipment office.)	
In this bay, the equipment that you will need has been organized for you. It will include: Comcheks, Trip Sheets, Paper Log Book, Load Locks, Tire Chains, Door Seals.	